

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/15/2020

Submitted Date:

04/15/2020

Document Number:

700700482

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 Ramsey, Scott 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		scollett@grizzlyenergyllc.com	
, Grizzly		bdixon@grizzlyenergyllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440033	GAS COMPRESSOR STATION	AC	11/20/2014		-	BAILEY COMPRESSOR #1 STATION	AC
440034	GAS COMPRESSOR STATION	AC	11/20/2014		-	BAILEY COMPRESSOR #2 STATION	AC
440035	GAS COMPRESSOR STATION	AC	11/20/2014		-	BAILEY COMPRESSOR #3 STATION	AC
440036	GAS COMPRESSOR STATION	AC	11/20/2014		-	BAILEY COMPRESSOR #4 STATION	AC
440037	GAS COMPRESSOR STATION	AC	11/20/2014		-	BAILEY COMPRESSOR #5 STATION	AC
440038	GAS COMPRESSOR STATION	AC	11/20/2014		-	BAILEY COMPRESSOR #6 STATION	AC

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 4/15/20 at approximately 9:30 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at Grizzly Bailey compressor station, at Facility # 412030 in Garfield Colorado.

While there, I observed normal operations. All C/A(s) from previous inspection document # 700700148 have been completed. Inventory remains the same.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	compressors		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	all unused equipment has been removed		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: <u>440033</u>	Type: <u>GAS</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>440034</u>	Type: <u>GAS</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>440035</u>	Type: <u>GAS</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>440036</u>	Type: <u>GAS</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>440037</u>	Type: <u>GAS</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>440038</u>	Type: <u>GAS</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>

**Environmental****Spill/Remediation:**Comment: Corrective  
Action: Date: Emission Control Burner (ECB): YESComment: Pilot: ONWildlife Protection Devices (fired vessels): YES**COGCC Comments**

Comment	User	Date
<a href="#">This is a compressor station follow up inspection.</a>	ramseys	04/15/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700488	Bailey compressor station re inspect	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5124753">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5124753</a>