

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /13NWNW

Location ID: 312601



Photo #0978 from entrance to location




Photo #0979 Tank capacity not labeled.



## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /13NWNW

Location ID: 312601



**Photo #0980 Multiple places with debris on location.**



**Photo #0981 Multiple places with debris on location.**