

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 1. Overview of location taken facing southwest.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 2. Missing or incomplete tank labels.



Photo 3. Missing or incomplete tank labels.

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 4. Sediment transport off location. Photo taken on access road looking uphill to location.



Photo 5. Sediment transport down access road ditch. Photo taken from same spot as photo 4 but looking down access road ditch away from location.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 6. Sediment transport off location. Photo taken standing on location perimeter looking towards access road.



Photo 7. Example of rill leaving access road.

