

Inspection Photos

Loc#311750

Operator: Laramie

Inspection #: 692402087

Inspection Date: 4/13/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

April 13, 2020



Photo#2:
Debris on site.



Photo#3:
Close up of Debris in Photo #2.

April 13, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Hells Gulch Fed Loc#311750



Photo#4:
Loose soil with no down gradient BMP.



Photo#5:
Rutting on Pad on Southwest corner

April 13, 2020



Photo#6:
Cut slope; initiating erosion.



Photo#7:
Cut slope and soil migration.

April 13, 2020