



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Calamity Ridge 4401D-A23-1N100 API: 05-103-10561
Inspection: 700401067








40.04614, -108.57598, 6881.9ft, 161°
04/15/2020 04:27:31 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tank.

Calamity Ridge 4401D-A23-1N100 API: 05-103-10561
Inspection: 700401067



40.04608, -108.57556, 6867.5ft, 75°

04/15/2020 04:21:26 PM

**IN CASE OF EMERGENCY
CONTACT 1-970-361-3007**

CONDENSATE



40.0461, -108.57593, 6888.4ft, 180°
04/15/2020 04:26:42 PM



40.04608, -108.57587, 6884.3ft, 113°
04/15/2020 04:27:06 PM





40.04647, -108.57512, 6880.9ft, 86°
04/15/2020 04:25:22 PM



40.04622, -108.57544, 6873.3ft, 37°

04/15/2020 04:22:12 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 10. Well head.

Calamity Ridge 4401D-A23-1N100 API: 05-103-10561
Inspection: 700401067



40.04619, -108.57538, 6870.4ft, 38°
04/15/2020 04:22:21 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 11. Pump jack vegetation.

Calamity Ridge 4401D-A23-1N100 API: 05-103-10561
Inspection: 700401067