



40.04833, -108.58401, 6824.0ft, 348°
04/15/2020 04:42:24 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Calamity Ridge 14-15C-1N100 API: 05-103-10462
Inspection: 700401069



40.04892, -108.58409, 6820.9ft, 148°
04/15/2020 04:40:11 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Calamity Ridge 14-15C-1N100 API: 05-103-10462
Inspection: 700401069



40.04905, -108.58405, 6810.9ft, 242°
04/15/2020 04:37:06 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Meter building.

Calamity Ridge 14-15C-1N100 API: 05-103-10462
Inspection: 700401069



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tank.

Calamity Ridge 14-15C-1N100 API: 05-103-10462
Inspection: 700401069



40.04886, -108.58356, 6833.4ft, 295°
04/15/2020 04:44:51 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Temporary & permanent tanks.

Calamity Ridge 14-15C-1N100 API: 05-103-10462
Inspection: 700401069



IN CASE OF EMERGENCY
CONTACT 1-970-361-3007

40.04913, -108.58391, 6823.4ft, 252°
04/15/2020 04:37:40 PM



40.04912, -108.58399, 6823.3ft, 23°
04/15/2020 04:39:08 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 8. Tank stack without bird protection.

Calamity Ridge 14-15C-1N100 API: 05-103-10462
Inspection: 700401069



40.0489, -108.58384, 6820.1ft, 166°
04/15/2020 04:44:12 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 9. Storm water sediment run on to location.

Calamity Ridge 14-15C-1N100 API: 05-103-10462
Inspection: 700401069



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 10. Fallen deadman marker.

Calamity Ridge 14-15C-1N100 API: 05-103-10462
Inspection: 700401069



40.04847, -108.58408, 6802.4ft, 90°
04/15/2020 04:41:33 PM