


## Inspection Photos

Location Name: HOWARD A-66N64W /27NESE

Location #: 305348



**Photo #1**

**Howard A 27-9 (05-123-22832) Wellsite**

**Temporarily Abandoned | TA**



**Photo #2**

**Howard A 27-9, 27-16 Battery site**

**Abandoned: All Equipment Removed**

*Reclamation progressing*