

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/15/2020

Submitted Date:

04/15/2020

Document Number:

701000489

**FIELD INSPECTION FORM**

Loc ID 302995 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252233	WELL	PR	01/18/2018	GW	125-06102	WHOMBLE 1-6	PR

**General Comment:**

Routine Inspection

*(This area is intentionally left blank for additional notes or observations.)*

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease sign for associated wells mounted to meter shed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead, VGS and meter shed		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:		Date:	
Type: Vertical Separator	# 5		
Comment:	5-Vertical gas separators 50% buried by meter shed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:	Shared meter run for (Whomble 1-6, 5-6, 8-6, 9-6 & Whomble 2-5)		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 252233 Type: WELL API Number: 125-06102 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Central meter run for \(Whomble 1-6, 5-6, 8-6, 9-6 & 2-5\)](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment: Access has erosion near location and needs maintenance

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT