

Inspection Photos

API: 071-06408

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/15/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06408 | Date: 4/15/2020

Inspection Photos



Photo 1. Facing south toward the location. The location has been seeded and seed appears to have been raked into soil.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06408 | Date: 4/15/2020

Inspection Photos



Photo 2. View of groundcover. Seed was observed and appears to have been reked into soil.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06408 | Date: 4/15/2020