

Inspection Photos

API: 071-09239

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/15/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09239 | Date: 4/15/2020

Inspection Photos



Photo 1. Well sign posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09239 | Date: 4/15/2020

Inspection Photos



Photo 2. The electric fence around the pit has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09239 | Date: 4/15/2020

Inspection Photos



Photo 3. The oil on engine skid has been cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09239 | Date: 4/15/2020