

# Inspection Photos

API: 071-09238

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/15/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09238 | Date: 4/15/2020

## Inspection Photos



**Photo 1.** Facing southeast along the main lease road ascending the hill. The road has been graded since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09238 | Date: 4/15/2020



## Inspection Photos



**Photo 2.** The culvert along the main lease road has been maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09238 | Date: 4/15/2020



## Inspection Photos



**Photo 3.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09238 | Date: 4/15/2020

## Inspection Photos



**Photo 4.** Unused equipment has been removed which was by the engine skid.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09238 | Date: 4/15/2020



## Inspection Photos



**Photo 5.** The is oily water has been cleaned up at the engine skid.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09238 | Date: 4/15/2020

## Inspection Photos



**Photo 6.** There is oily waste has been cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09238 | Date: 4/15/2020