

Inspection Photos

API: 071-09236

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/15/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 4/15/2020

Inspection Photos



Photo 1. The culvert along the main lease road ascending the hill has been maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 4/15/2020

Inspection Photos



Photo 2. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 4/15/2020

Inspection Photos



Photo 3. There is oil stained soil has been cleaned up around the engine skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 4/15/2020

Inspection Photos



Photo 4. The unused sound walls have been removed from the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 4/15/2020

Inspection Photos



Photo 5. The road has been regraded where erosion was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 4/15/2020