

# Final Reclamation and Stormwater Inspection

April 15, 2020

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 426701

Inspection Document #: 697501358

Weld County, CO

Lot 3 Section 1 T7N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location: Bridgman #1-1H  
Location ID: 426701



**Photo 1.** Photo taken from the entrance of location, facing South. Photo illustrates Operator is in-process of performing final reclamation.

Inspection Photos  
Location: Bridgman #1-1H  
Location ID: 426701



**Photo 2.** Photo taken from the northern location, facing South. See comments under Photo 1. Appears the Operator is starting to spread topsoil. Operator shall cross-rip disturbance areas to a depth of 18" prior to spreading topsoil.  
Note: There is a ditch and berm around the downgradient perimeter of location.

Inspection Photos  
Location: Bridgman #1-1H  
Location ID: 426701



**Photo 3.** Photo taken from the northern location, facing East. See comments under Photo 1 and 2.

Inspection Photos  
Location: Bridgman #1-1H  
Location ID: 426701



**Photo 4.** Photo taken from the northern location, facing South. See comments under Photo 1 and 2.