



39.88738, -108.80485, 6502.3ft, 9°
04/17/2020 04:10:44 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

North Douglas Creek 9-11-2-2 API: 05-103-07778
Inspection: 700401099



39.88748, -108.80469, 6517.6ft, 350°
04/17/2020 04:12:21 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Separator & meter building.

North Douglas Creek 9-11-2-2 API: 05-103-07778
Inspection: 700401099



39.88761, -108.80485, 6519.9ft, 64°
04/17/2020 04:11:22 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Tank.

North Douglas Creek 9-11-2-2 API: 05-103-07778
Inspection: 700401099



39.88754, -108.80472, 6514.7ft, 312°
04/17/2020 04:11:52 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Pit & tank.

North Douglas Creek 9-11-2-2 API: 05-103-07778
Inspection: 700401099