




39.89374, -108 77923, 6528 0ft, 340°
04/17/2020 04:50:21 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

North Douglas Creek 3-7-2-1 API: 05-103-07775
Inspection: 700401106







39.89393, -108.77924, 6539.3ft, 50°
04/17/2020 04:50:59 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tank.

North Douglas Creek 3-7-2-1 API: 05-103-07775
Inspection: 700401106



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Pit, tank & separator.

North Douglas Creek 3-7-2-1 API: 05-103-07775
Inspection: 700401106