

Inspection Photos
Location Name: Tiffany Gathering Line
Spill/Release Point ID: 474977



Tiffany Gathering Line Release location photo.



Point source where produced water daylighted.

Inspection Photos
Location Name: Tiffany Gathering Line
Spill/Release Point ID: 474977



Staining along flow path.



Temporary fencing installed to prevent access by livestock.

Inspection Photos
Location Name: Tiffany Gathering Line
Spill/Release Point ID: 474977



Flow path terminates in an agricultural wetland.



View looking back towards point source from below termination of flow path.