

Inspection Photos

API: 071-07697

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/16/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07697 | Date: 4/16/2020

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07697 | Date: 4/16/2020

Inspection Photos



Photo 2. This area is bare of vegetation at the west side of the location and needs additional seeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07697 | Date: 4/16/2020

Inspection Photos



Photo 3. Facing back toward the south. This area needs additional seeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07697 | Date: 4/16/2020

Inspection Photos



Photo 4. Facing south at the east side of the location. Vegetation is well established along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07697 | Date: 4/16/2020