

Inspection Photos

API: 071-06609

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/16/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06609 | Date: 4/16/2020

Inspection Photos



Photo 1. There is an erosion gully that has form along the main road at Lat/Long:37.081525,-104.69693.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06609 | Date: 4/16/2020

Inspection Photos



Photo 2. There is erosion occurring along the main road ascending the hill to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06609 | Date: 4/16/2020

Inspection Photos



Photo 3. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06609 | Date: 4/16/2020

Inspection Photos



Photo 4. Well sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06609 | Date: 4/16/2020