

## Inspection Photos

Location Name: GOLDEN EAGLE 17-15

API#: 05-071-07775

INSP. #: 695102716



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

## Inspection Photos

Location Name: GOLDEN EAGLE 17-15

API#: 05-071-07775

INSP. #: 695102716



Colorado Oil & Gas Conservation Commission  
37.16674, -104.9072, 2334.0m, 329°  
2020/04/20 12:55:40



Colorado Oil & Gas Conservation Commission  
37.16674, -104.9072, 2337.0m, 42°  
2020/04/20 12:55:50

**PHOTO 3: AREA OF IMPACTED SOIL NEAR ENGINE SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-25-20.**

**PHOTO 4: THERE IS STANDING OIL IN ENGINE SKID. Comply with general provisions of the oil and gas act for wildlife protection. CA DATE 5-20-20**