

Inspection Photos  
Location Name: Breniman 16-B  
Location ID: 439436



Photo 1: Wellhead Sign



Photo 2: Stained soil removed

Inspection Photos  
Location Name: Breniman 16-B  
Location ID: 439436



Photo 3: Wellhead Sign



Photo 4: Stained soil removed

Inspection Photos  
Location Name: Breniman 16-B  
Location ID: 439436



Photo 5: Wellhead Sign



Photo 6: Stained soil removed

Inspection Photos  
Location Name: Breniman 16-B  
Location ID: 439436



Photo 7: Wellhead Sign



Photo 8: Equipment removed

Inspection Photos  
Location Name: Breniman 16-B  
Location ID: 439436



Photo 9: NFPA placard installed



Photo 10: NFPA placard installed

**Inspection Photos**  
**Location Name: Breniman 16-B**  
**Location ID: 439436**



**Photo 11: Unused risers**