

Inspection Photos
Location Name: Winder North Pad
Location ID: 430438



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Winder North Pad
Location ID: 430438



Photo 3: Wellhead Sign



Photo 4: Stained soil removed

Inspection Photos
Location Name: Winder North Pad
Location ID: 430438



Photo 5: Insulation removed



Photo 6: Insulation removed

Inspection Photos
Location Name: Winder North Pad
Location ID: 430438



Colorado Oil and Gas Conservation Commission
40.50739, -104.89194, 1479.5m, 37°
Apr 20, 2020 12:39:45

Photo 7: Insulation removed; STORAGE OF UNUSED EQUIPMENT



Colorado Oil and Gas Conservation Commission
40.50771, -104.89171, 1466.5m, 214°
Apr 20, 2020 12:40:52

Photo 8: Unused equipment

Inspection Photos
Location Name: Winder North Pad
Location ID: 430438



Photo 9: Unused equipment



Photo 10: Unused equipment

Inspection Photos
Location Name: Winder North Pad
Location ID: 430438



Photo 11: No wellhead signage