

**Inspection Photos**  
**Location Name: Gurtler 2A-30H & 2B-30H**  
**Location ID: 429963**



**Photo 1 WH sign**



**Photo 2 WH**

Inspection Photos  
Location Name: Gurtler 2A-30H & 2B-30H  
Location ID: 429963



Photo 3 WH sign



Photo 4 WH



Inspection Photos  
Location Name: Gurtler 2A-30H & 2B-30H  
Location ID: 429963



Colorado Oil & Gas Conservation Commission  
24072 Co Rd 18, Keenesburg, CO 80643, USA  
40.11641, -104.60146, 4882.9ft, 87°  
04/20/2020 12:56:28



Colorado Oil & Gas Conservation Commission  
24076 Co Rd 18, Keenesburg, CO 80643, USA  
40.11642, -104.60139, 4882.9ft, 42°  
04/20/2020 12:57:31

Photo 5 TB signs

Photo 6 TB



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Gurtler 2A-30H & 2B-30H**  
**Location ID: 429963**



**Photo 7 ECDs**



**Photo 8 Heated horiz.sep. and vertical sep.**

**Inspection Photos**  
**Location Name: Gurtler 2A-30H & 2B-30H**  
**Location ID: 429963**



**Photo 9 Compressor**



**Photo 10 Gas meter run**





**Location ID: 429963**



**Photo 12 Stained soil by fill line at tank battery.**

**Inspection Photos**  
**Location Name: Gurtler 2A-30H & 2B-30H**  
**Location ID: 429963**




**Photo 13 Stained soil by fill line at tank battery.**



**Photo 14 Stained soil by fill line at tank battery.**



**Inspection Photos**  
**Location Name: Gurtler 2A-30H & 2B-30H**  
**Location ID: 429963**



**Photo 15 Stained soil by fill line at tank battery.**



**Photo 16 Stained soil by fill line at tank battery, possible leak**