

Inspection Photos
Location Name: Ozbun 10-19
Location ID: 331666



Photo 1 WH sign

Photo 2 WH, weeds growing around AG fence

Inspection Photos
Location Name: Ozbun 10-19
Location ID: 331666




Photo 3 TB sign

Photo 4 TB

Inspection Photos
Location Name: Ozbun 10-19
Location ID: 331666



Colorado Oil & Gas Conservation Commission
 24509 Co Rd 18, Keenesburg, CO 80643, USA
 40.11686, -104.59372, 4886.0ft, 312
 04/20/2020 14:32:50



Date Inspected	Size	M.F.D. Coefficient	Test Date	Date	U.S. Reg/Prod
12-9-09	1.250		12-9-09	12-9-09	3.112
6-15-10	1.250		6-15-10	6-15-10	3.011
12-2-10	1.25		12-2-10	12-2-10	11.5 ppm
6-8-11	1.250		6-8-11	6-8-11	4.001
12-7-14	2.250	2.69	12-7-14	12-7-14	5.0
6-26-12	1.250		6-26-12	6-26-12	2.5
12-2-11	1.250		12-2-11	12-2-11	5.0
12-31-13	1.25		12-31-13		
6-25-14	1.250		6-25-14	6-25-14	2.0
12-16-14	1.25		12-16-14		
6-4-15	1.25		6-4-15	6-4-15	2.5 ppm
12-8-15	1.25		12-8-15	12-8-15	3 ppm
6-7-16	1.25		6-7-16	6-7-16	4 ppm
12-2-16	1.25		12-2-16	12-2-16	3 ppm
6-21-17	1.25		6-21-17	No Flow	
12-4-17	1.25		12-4-17	12-4-17	
6-20-18	1.25				
1-9-20	1.25				

Colorado Oil & Gas Conservation Commission
 24509 Co Rd 18, Keenesburg, CO 80643, USA
 40.11686, -104.59384, 4889.0ft, 339
 04/20/2020 14:33:19

Photo 5 Gas meter run

Photo 6 Card inside meter house

Inspection Photos
Location Name: Ozbun 10-19
Location ID: 331666



Photo 7 Horizontal Heated Separator

Photo 8 ECD weeds growing around/inside AG fence