

Inspection Photos
Location Name:
Popham Tank Battery Location
Location ID: 448866



Photo #1 Lacts



Photo #2 Air Compressors

Inspection Photos
Location Name:
Popham Tank Battery Location
Location ID: 448866



Colorado Oil and Gas Conservation Commission
40.33895, -104.53722, 4641.1ft, 121°
04/21/2020 09:25:22 AM

Photo #3 Separators



Colorado Oil and Gas Conservation Commission
40.33884, -104.53701, 4631.6ft, 133°
04/21/2020 09:25:49 AM

Photo #4 ECD's

Inspection Photos
Location Name:
Popham Tank Battery Location
Location ID: 448866



Photo #5 Crude oil tanks & Pits



Photo #6 Produced Water Tanks

Inspection Photos
Location Name:
Popham Tank Battery Location
Location ID: 448866



Colorado Oil and Gas Conservation Commission
40.33908, -104.53737, 4626.5ft, 293°
04/21/2020 09:27:19 AM

Photo #7 Meter Runs



Colorado Oil and Gas Conservation Commission
40.33915, -104.53755, 4612.7ft, 196°
04/21/2020 09:27:37 AM

Photo #8 Separators

Inspection Photos
Location Name:
Popham Tank Battery Location
Location ID: 448866



Photo #9 Compressors & VRU



Photo #10 Meter Runs

Inspection Photos
Location Name:
Popham Tank Battery Location
Location ID: 448866



Photo #11 Pig Station