

**Inspection Photos**  
**Location Name: Vera L McCannon 1**  
**Location ID: 159787**



**Pic 1**



**Pic 2 stained soil around tanks**

**Inspection Photos**  
**Location Name: Vera L McCannon 1**  
**Location ID: 159787**




**Pic 3 no BMP under barrel in pump house**



**Pic 4**



**Inspection Photos**  
**Location Name: Vera L McCannon 1**  
**Location ID: 159787**



**Pic 5 mechanical issue with separator**



**Pic 6 Calibration date 2011**