

Final Reclamation Inspection

April 20, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 328083

Inspection Document #: 697501382

Weld County, CO

NWSW Section 16 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WEIDERSPON ST #J16-12
Location ID: 328083



Photo 1. Photo taken from the well location entrance, facing East. Photo illustrates the gate was locked with livestock. COGCC staff will have to perform a future inspection to ensure all equipment was removed and that the well location meets vegetative standards.

Inspection Photos
Location Name: WEIDERSPON ST #J16-12
Location ID: 328083



Photo 2. Photo taken from the western access road for the associated offsite tank battery, facing East. See comments under Photo 1. Operator did perform final reclamation activities with the evidence of drill rows and straw crimped mulch. Germination of desirable species was sparse throughout the access road compared to the tank battery..

Inspection Photos
Location Name: WEIDERSPON ST #J16-12
Location ID: 328083



Photo 3. Photo taken from the western access road for the associated offsite tank battery, facing East. Photo illustrates what appears to be a stabilized retention area for stormwater related to the housing development.

Inspection Photos
Location Name: WEIDERSPON ST #J16-12
Location ID: 328083



Photo 4. Photo taken from a portion of the access road for the associated offsite tank battery, facing East. See comments under Photo 2.

Inspection Photos
Location Name: WEIDERSPON ST #J16-12
Location ID: 328083



Photo 5. Photo taken from the associated offsite tank battery, facing North. Photo illustrates Operator performed final reclamation activities with the evidence of drill rows, straw crimped mulch, and germination of desirable species.