



Inspection Photos

Well 057-06261

Inspection Date: 4/10/2020

All Photos taken by Kris Neidel

Photo #1 Sign on pump jack



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #2 Wellhead of Conoco #34



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #3 Access road from Conoco #34 well. Well is behind camera. From Conversation on 4/14/20 with the operator, the Area where road turns to the left, is where an injection line failed in 2020.



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #4 Access road from Conoco #34 well. Well is behind camera. From Conversation on 4/14/20 with the operator, the Area where road turns to the left, is where an injection line failed in 2020.



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #5 It was stated by Operator on 4/14/20 that disturbed dirt in foreground is from a recent IJ line release. The area in the back right of photo is remaining impact from a 2018 release.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #6 recently disturbed soil.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Well 057-06261

Inspection Date: 4/10/2020

All Photos taken by Kris Neidel



Photo #7 This area was discussed with the operator on 4/14/20. It was stated that this is the result of a 2018 release. The release was not reported to COGCC.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #8. Dark soil smells of hydrocarbon. This area was discussed with the operator on 4/14/20. It was stated that this is the result of a 2018 release.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #9 Close up of remaining impact from 2018 release.



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #10 Close up of remaining impact from 2018 release.



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #11 Dark soil smells of hydrocarbon. This area was discussed with the operator on 4/14/20. It was stated that this is the result of a 2018 release.



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #12 Dark soil smells of hydrocarbon. The Operator reported that this is impact remaining from a 2018 release.



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #13 Impact remaining on game trail.



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #14 Dark soil smells of hydrocarbon. The Operator reported that this is impact remaining from a 2018 release.



Inspection Photos
Well 057-06261
Inspection Date: 4/10/2020
All Photos taken by Kris Neidel

Photo #15 debris near the access road to Conoco #34 well.