

Inspection Photos
Location Name: Vail Pad
Location ID: 443507




Location entrance




Wellheads

Inspection Photos
Location Name: Vail Pad
Location ID: 443507



Stained soil



Stained soil

Inspection Photos
Location Name: Vail Pad
Location ID: 443507



Stained soil



VRT placards

Inspection Photos
Location Name: Vail Pad
Location ID: 443507



Lube oil storage



Chemical storage

Inspection Photos
Location Name: Vail Pad
Location ID: 443507



Trash



Trash

Inspection Photos
Location Name: Vail Pad
Location ID: 443507



Trash




Trash

Inspection Photos
Location Name: Vail Pad
Location ID: 443507



Colorado Oil And Gas Conservation Commission
40.32863, -104.95915, 1483.0m
04/22/2020 12:55:26 PM

Trash



Colorado Oil And Gas Conservation Commission
40.32863, -104.95924, 1478.0m
04/22/2020 12:54:22 PM

Meter calibration card