

## Inspection Photos

Location Name: Kerr McGee Held 12-1418

Location: 330322, Spill/Release: 467174



**Affected reach of the ditch.**



**Excavation to expose the release point.**





## Inspection Photos

Location Name: Kerr McGee Held 12-1418

Location: 330322, Spill/Release: 467174



**Impacted soil in open excavation near release point.**



**Temporary dam in the ditch.**





## Inspection Photos

Location Name: Kerr McGee Held 12-1418

Location: 330322, Spill/Release: 467174



**Pumping to manage water above the temporary dam.**



**Pumping above the temporary dam.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources