

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 4/10/2020  
All Photos taken by Kris Neidel



Photo #1 Aerial Photo, provided to give context to photos.  
Berm west of tanks separates the tank battery from lower level  
secondary containment.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #2 tank label. Tank Battery sign was not observed.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel

Photo #3 evidence of soil removed from upper secondary containment/Main tank battery. Tank in Photo is southeast most tank. Close up in photo #7.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #4 remaining impact at spill 473059 spill area inside of upper tank battery. Stairs seen in photo is to the large diameter tank seen in Photo #1

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #5 looking south. Hydrocarbon impact remaining in tank battery.

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #6 Hydrocarbon impact remaining.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel

Photo #7 close up of photo #3.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #8 close up of tank battery.

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #9 tank load out.





Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel

Photo #10 tank Battery



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #11 where backhoe tracks turn to the left of photo, was the area seen in 3/10/20 inspection where oil had seeped through to the lower secondary containment.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #12 road down to stockpiled soil inside lower secondary containment.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel

Photo #13 estimated 20x40x3 volume of soil. Stored in secondary containment. From communication with operator, soil is being hauled for disposal at a commercial facility.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel

Photo #14 southwest most corner of lower secondary containment.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #15 southwest most corner of lower secondary containment.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #16 close-up of stored soil.

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #17 separation equipment at facility.

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #18 separation equipment at facility.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #19 separation equipment at facility.





Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel

Photo #20 separation equipment at facility.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #21 separation equipment at facility.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #22 Dwinell Injection Well





Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel

Photo #23 pit near IJ well.





Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel

Photo #24 close-up of pit.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel

Photo #25 Close-up of pit netting.

