

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2020

Submitted Date:

04/22/2020

Document Number:

696102790**FIELD INSPECTION FORM**Loc ID: 305891 Inspector Name: Evins, Bret On-Site Inspection: ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283279	WELL	PA	10/20/2016	OW	123-23628	SHARKEY 31-35	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Active.

Centralized Battery serves 2 Location IDs (305365, 305251).
(Well(s): 2: Producing | PR).

Centralized Battery formerly served 1 Location ID (305891).
(Well(s): 1: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696102788 and/or Location ID #305365
for Battery / Facility, Equipment info.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Gas Meter Run

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Horizontal Heated Separator

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Emission Control Device

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date: **Paint**Condition: Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input type="text"/>			<input type="text"/>
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment:		Plugged & Abandoned PA. Equipment removed.				
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No						
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 283279 Type: WELL API Number: 123-23628 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 04/22/2020 at approximately 16:15 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: SHARKEY-66N64W /35NWNE Location ID: 305891 Well Name: Sharkey 31-35 API: 05-123-23628 Location County: Weld County, Colorado Weather: Partltly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Active.</p> <p>Centralized Battery serves 2 Location IDs (305365, 305251). (Well(s): 2: Producing PR).</p> <p>Centralized Battery formerly served 1 Location ID (305891). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696102788 and/or Location ID #305365 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #401150095 indicates plugging, cut/cap date: 10/20/2016. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/22/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102791	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5130313