





39.95519, -108.9933, 5931.3ft, 11°
04/22/2020 12:43:45 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Locaton.


Banta Ridge 1-18-1-103 API: 05-103-10155
Inspection: 700401159



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well head.

Banta Ridge 1-18-1-103 API: 05-103-10155
Inspection: 700401159





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tank.

Banta Ridge 1-18-1-103 API: 05-103-10155
Inspection: 700401159