

Inspection Photos
Location Name: Purcell PC GK 11-10
Location ID: 419904



Photo 1 – Pumping Unit



Photo 2 – Unmarked Risers, Unused Wellhead parts

Inspection Photos
Location Name: Purcell PC GK 11-10
Location ID: 419904




Photo 3 – Unused Wellhead parts and Chemical Tank, Secondary Containment and Stand



Photo 4 – Unused Chemical Tank, stands and Secondary Containment