

Final Reclamation Inspection

April 22, 2020

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 333142

Inspection Document #: 697501392

Weld County, CO

SWSW Section 34 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SELTZER #14-34
Location ID: 333142



Photo 1. Google Earth aerial imagery from 9/12/2019 illustrates an area circled in red that is subject to comply with COGCC rules and regulation. Other portions of the eastern access road are within a final land use change (i.e., storage facility).

Inspection Photos
Location Name: SELTZER #14-34
Location ID: 333142



Photo 2. Photo taken from the associated offsite tank battery, facing Northwest. Photo illustrates tank battery is in use for other nearby wells.

Inspection Photos
Location Name: SELTZER #14-34
Location ID: 333142



Photo 3. Photo taken from the well location, facing East. Photo illustrates there is no evidence to suggest final reclamation activities were completed. Annual, weedy vegetation with bare ground was observed.

Inspection Photos
Location Name: SELTZER #14-34
Location ID: 333142



Photo 4. Photo taken from a portion of the well location access road, facing East. See comments under Photo 3.

Inspection Photos
Location Name: SELTZER #14-34
Location ID: 333142



Photo 5. Photo taken from a portion of the well location access road, facing East. Photo illustrates a portion of the well location access road has been disturbed by the construction of a storage facility (final land use change).

Inspection Photos
Location Name: SELTZER #14-34
Location ID: 333142



Photo 6. Reference photo taken west of the well location, facing West. Photo illustrates vegetation mostly consists of crested wheatgrass.