

# Final Reclamation Inspection

April 22, 2020

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 405998

Inspection Document #: 697501394

Weld County, CO

NWSE Section 33 T1N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name:  
AMOCO-CHARTER-SCHNEIDER #1  
Location ID: 405998



**Photo 1.** Photo taken from the location of the former AMOCO-CHARTER-SCHNEIDER #1 well, facing West. Operator shall remove all remaining equipment per Rule 1004.a.

Inspection Photos  
Location Name:  
AMOCO-CHARTER-SCHNEIDER #1  
Location ID: 405998



**Photo 2.** Photo taken of the associated offsite tank battery, facing North. Photo illustrates tank battery is still in use by other nearby wells. Appears dirt work was being performed at the time of this inspection.