

Inspection Photos
Location Name: Federal 5-27X
Location ID: 324684



Photo 1. Overview of location taken facing east.



Photo 2. Stained soil at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources