

# Inspection Photos

API: 055-06302

Operator: TABULA RASA ENERGY

Inspection Date: 4/22/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06302 | Date: 4/22/2020

## Inspection Photos



**Photo 1.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06302 | Date: 4/22/2020



## Inspection Photos



**Photo 2.** Well sign is posted at the well head. Emergency contact number on the sign needs to be updated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06302 | Date: 4/22/2020



## Inspection Photos



**Photo 3.** Facing northwest at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06302 | Date: 4/22/2020