

# Final Reclamation Inspection

April 22, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 319847

Inspection Document #: 697501398

Adams County, CO

NENE Section 3 T1S R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: JOHN WEIGANDT GAS UNIT #1

Location ID: 319847



**Photo 1.** Photo taken from the plugged and abandoned location, facing South. Photo illustrates well location and reference crop areas appear to be fallow. A follow up inspection will be conducting to document vegetative growth during an active growing season.

Inspection Photos

Location Name: JOHN WEIGANDT GAS UNIT #1

Location ID: 319847



**Photo 2.** Photo taken from the associated offsite tank battery, facing South. Photo illustrates Operator has performed final reclamation activities with the evidence of desirable plant species establishment.

Inspection Photos

Location Name: JOHN WEIGANDT GAS UNIT #1

Location ID: 319847



**Photo 3.** Photo taken from the associated offsite tank battery, facing North. Photo illustrates vegetative levels of surrounding areas.

Inspection Photos

Location Name: JOHN WEIGANDT GAS UNIT #1

Location ID: 319847



**Photo 4.** Photo taken from the associated offsite tank battery, facing East. See comments under Photo 3.