

Final Reclamation Inspection

April 22, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 320368

Inspection Document #: 697501400

Adams County, CO

NESW Section 3 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SELTZER #23-3
Location ID: 320368



Photo 1. Photo taken from the entrance of the plugged and abandoned location, facing South. Photo illustrates Operator has performed final reclamation activities with the evidence of straw crimped mulch and drill rows.

Inspection Photos
Location Name: SELTZER #23-3
Location ID: 320368



Photo 2. Photo taken from the northwestern location, facing East. See comments under Photo 1.