

Inspection Photos
Location Name: Gobbler Tank Battery 1C-23HZ
Location ID: 425962



Photo 1 TB location



Photo 2 TB signs

Inspection Photos
Location Name: Gobbler Tank Battery 1C-23HZ
Location ID: 425962



Photo 3 TB



Photo 4 LACT

Inspection Photos
Location Name: Gobbler Tank Battery 1C-23HZ
Location ID: 425962



Photo 5 Vertical Separator



Photo 6 Compressors and electric panels

Inspection Photos
Location Name: Gobbler Tank Battery 1C-23HZ
Location ID: 425962



Photo 7 Vertical Separator



Photo 8 Horizontal Heated Separators

Inspection Photos
Location Name: Gobbler Tank Battery 1C-23HZ
Location ID: 425962



Photo 9 Horizontal Heated Separators

Photo 10 ECDs

Location ID: 425962



Photo 13 Gas Meter run



Photo 14 Card inside North meter house