

Inspection Photos
Location Name: Elaine 43-28
Location ID: 336320



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Elaine 43-28
Location ID: 336320



Photo 3 Stained soil under pump jack counter weights



Photo 4 Stained soil under pump jack counter weights

Inspection Photos
Location Name: Elaine 43-28
Location ID: 336320



Photo 5 TB sign



Photo 6 TB

Inspection Photos
Location Name: Elaine 43-28
Location ID: 336320



Photo 7 Horizontal Heated Separator