

Inspection Photos
Location Name: Marconi 1-1H
Location ID: 423680



Photo 1 – Tank Battery



Photo 2 – Unused Pipe in SW Corner of Location

Inspection Photos
Location Name: Marconi 1-1H
Location ID: 423680




Photo 3 – Unmarked Risers




Photo 4 – Unmarked Risers

Inspection Photos
Location Name: Marconi 1-1H
Location ID: 423680



Photo 5 – Stained Soil inside the Engine Housing



Photo 6 – Stained Soil inside the Engine Housing

Inspection Photos
Location Name: Marconi 1-1H
Location ID: 423680



Photo 7 – Stained Soil at Exhaust



Photo 8 – Stained Soil at front of Pumping Unit