

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457



Photo 1 – Tank Battery



Photo 2 – Signage



Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457




Photo 3 – Stained Soil at Wellhead




Photo 4 – Stained Soil at Wellhead

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457




Photo 5 – Stained Soil at Wellhead



Photo 6 – Stained Soil at Exhaust

Inspection Photos
Location Name: Dunn 1-13H
Location ID: 426457




Photo 7 – Stained Soil at Engine



Photo 8 – Stained Soil at Pumping Unit