



39.96705, -109.00013, 5633.6ft, 295°
04/22/2020 04:01:39 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Banta Ridge 14-18-1-103 API: 05-103-10426
Inspection: 700401185



39.96707, -109.00027, 5644.7ft, 329°
04/22/2020 04:02:02 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Banta Ridge 14-18-1-103 API: 05-103-10426
Inspection: 700401185



39.96733, -109.00041, 5650.8ft, 5°
04/22/2020 04:02:46 PM



