



39.96022, -108.99843, 5828.8ft, 33°
04/22/2020 04:18:00 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Banta Ridge 7-18-1-103 API: 05-103-10386
Inspection: 700401187



39.96057, -108.99809, 5816.3ft, 67°
04/22/2020 04:15:51 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Banta Ridge 7-18-1-103 API: 05-103-10386
Inspection: 700401187





39.96079, -108.99802, 5811.0ft, 26°
04/22/2020 04:16:18 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tanks.

Banta Ridge 7-18-1-103 API: 05-103-10386
Inspection: 700401187