

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /17SWSW

Location ID: 334066



**Photo #1038 from entrance to location**



**Photo #1039 Multiple places with trash on location.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /17SWSW

Location ID: 334066



**Photo #0887 from inspection #699800830 conducted on 4/1/20.**




**Photo #1040 Multiple places with trash on location.**




## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /17SWSW

Location ID: 334066



**Photo #0888 from inspection #699800830 conducted on 4/1/20.**



**Photo #1041 Multiple places with trash on location.**

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /17SWSW**

**Location ID: 334066**



**Photo #0889 from inspection #699800830 conducted on 4/1/20.**