

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 1 WH sign**



**Photo 2 Stained soil around WH**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 3 Electric panel, meter box and transformers.**



**Photo 4 Pump Jack**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 5 TB signs**



**Photo 6 TB**



**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 7 stained soil by TB valve.**



**Photo 8 stained soil by TB valve/service line.**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 9 stained soil inside separator house, trash.**



**Photo 10 stained soil inside separator house**



**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 11 Gas meter runs**



**Photo 12 separator house door in disrepair.**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 13 Horizontal heated separator**



**Photo 14 fencing around Horiz. Heated separator in disrepair.**