

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2020

Submitted Date:

04/25/2020

Document Number:

696102824

FIELD INSPECTION FORM

Loc ID 310552 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------------|---------------------------------|
| , | | NBL_DJBU_Inspections@nblenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 293536 | WELL | SI | 11/01/2017 | OW | 123-26571 | LANDWEHR A 34-4 | SI |

General Comment:

This is a WELL / BATTERY inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (310552, 310553).
(Well(s): 2: Shut-In | SI).

| Location | | | |
|--|-----------------------------|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action: | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Iron panel. | | |
| Corrective Action: | | | Date: |
| Type | SEPARATOR | | |
| Comment: | Surrounded by earth berms. | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Bradenhead | # 1 | | corrective date |
| Comment: | Appears plumbed to surface. | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------------------|--|--|-------|
| Type: Ancillary equipment | # 1 | | |
| Comment: | ECD scrubber. | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 1 | | |
| Comment: | Controls crude oil tanks VOCs. Pilots: OFF Shut-down. | | |
| Corrective Action: | | | Date: |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: | Centralized Battery serves 2 Location IDs (310552, 310553). | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|--------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | <100 BBLS | CONCRETE SUMP/VAULT | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|-----------|--|
| Condition | |
|-----------|--|

| | |
|---------------------------|--|
| Other (Content) | |
| Other (Capacity) 53 Bbls. | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |

| | | | |
|--------------------|----------------------------------|-------|--|
| Comment: | Shares berms w/ crude oil tanks. | | |
| Corrective Action: | | Date: | |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|-----------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 40.448609,-104.545445 |

| | | | |
|--------------------|--|-------|--|
| Comment: | Equalizer line connects crude oil tanks. | | |
| Corrective Action: | | Date: | |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |

| | | | |
|--------------------|-------------------------------------|-------|--|
| Comment: | Shares berms w/ produced H2O vault. | | |
| Corrective Action: | | Date: | |

Venting:

| | |
|--------------------|----|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | |
| Date: | |

Flaring:

| | |
|--------------------|--|
| Type | |
| Comment: | |
| Corrective Action: | |
| Date: | |

Inspected Facilities

Facility ID: 293536 Type: WELL API Number: 123-26571 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
COGCC records indicate last production: 10/2017.
SI/TA well per variance doc. #401474555. (NOBLE).
Yellow LTSI tag for SI/TA status present at wellsite.
Locked-Out, Tagged-Out | LOTO.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary:</p> <p>On FRI 04/24/2020 at approximately 14:54 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: LANDWEHR A-66N64W /34NWNW Location ID: 310552 Well Name: Landwehr A 34-4 API: 05-123-26571 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (310552, 310553). (Well(s): 2: Shut-In SI).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 04/25/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696102825 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5132454 |