

## Inspection Photos

Location Name: HOWARD-BC A-66N64W /34NWNE

Location #: 327254



**Photo #1**

**Howard-BC A 34-02 (05-123-14394) Wellsite**

**Plugged & Abandoned | PA**

**~ 15 yds.**

*Reclamation progressing*



**Photo #2**

**Howard-BC A 34-02 Battery site**

**Abandoned: *ALL Equipment removed***

*Reclamation progressing*



## Inspection Photos

**Location Name:** HOWARD-BC A-66N64W /34NWNE

**Location #:** 327254



Colorado Oil and Gas Conservation Commission  
40.44766, -104.53471, 4600.1ft, 40°  
07/09/2019 11:30:36

**Photo #3**

**Howard-BC A 34-02** Wellsite  
**Temporarily Abandoned | TA**  
**Weeds / Unused Equipment**  
*prior insp.*



Colorado Oil & Gas Conservation Commission  
40.4478° N, -104.5347° W  
Apr 24, 2020 14:17

**Photo #4**


**Howard-BC A 34-02** Wellsite  
**Plugged & Abandoned | PA**  
*Weeds cleared. All Equipment removed.*



## Inspection Photos

Location Name: HOWARD-BC A-66N64W /34NWNE

Location #: 327254



**Photo #5**

**Howard-BC A 34-02 Battery site**

*Weeds / Unused Equipment*

*No Battery sign / No Emergency number posted  
prior insp.*



**Photo #6**

**Howard-BC A 34-02 Battery site**

*Abandoned: ALL Equipment removed*

*Weeds cleared*