

Inspection Photos
Location Name: Cox PM C 8-6
Location ID: 327111



Photo #1 Well & Sign



Photo #2 No variance tag



Inspection Photos
Location Name: Cox PM C 8-6
Location ID: 327111



Photo #3 Separator, ECD & Meter Run



Photo #4 Tank Battery



Inspection Photos
Location Name: Cox PM C 8-6
Location ID: 327111



Photo #5 Unreadable Capacity Label




Photo #6 Stained Soil



Inspection Photos
Location Name: Cox PM C 8-6
Location ID: 327111



Photo #7 Stained Soil



Photo #8 Stained Soil

